

# General Environmental Incident Summary

**Incident:** 3459      **Date/Time Notice:** 9/15/2014      1442      **DEM Incident No:**

**Responsible Party:** Trucking Company Unknown at this time

**Date Incident:** 9/15/2014      **Time Incident:** 0745      **Duration:**

**County:** Ward      **Twp:** 156      **Rng:** 87      **Sec:** 8      **Qtr:**

**Lat:** 48.34569      **Long:** -101.87960      **Method:** Interpolation from map

**Location Description:** Railroad Grade crossing at 380th St NW and BNSF Mile Post 30.8 Glasgow  
Subdivision Montana Division

**Submitted By:** Greg Jeffries

**Affiliation:** BNSF

**Address:** 80 44th Avenue NE

**City:** Minneapolis

**State:** MN

**Zip:** 55421

**Received By:**

**Contact Person:**

Unknown

Unknown, ND

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Diesel fuel from semi tractor

**Volume Spilled:** 50.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

Semi Truck struck a BNSF train at Grade crossing number DOT087177J

**Risk Evaluation:**

None

**# of Fatalities:** 1

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Impact to surface water possible but very unlikely.

**Action Taken or Planned:**

Fire Department put floor dry down to soak up product and absorbent booms to control run-off

**Wastes Disposal Location:**

**Agencies Involved:**

## **Updates**

---

**Date:** 9/15/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Train/truck accident released an estimated 50 gallons of diesel. Fire Department put down Floor Dry and placed absorbent booms. Followup is necessary. Inspection will be done by team member on 9/16/14.

---

**Date:** 9/16/2014    **Status:** Inspection

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

On location 09:30. Accident location on south side of BNSF crossing and west side of the township road. Minor fuel staining and faint odor of diesel remaining. No significantly stained soil remains. Area has been re-groomed after cleanup. No surface water in the area at risk. No further inspection or cleanup needed.